
# Appendix A. Setup Photographs

## <Conducted Emission>

## Mode 4



Mode 3




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJB008 Page Number : A1 of A3
Report Issued Date : Apr. 08, 2015
Report Version : Rev. 01

Report No.: FC530506


## <Radiated Emission>

## Mode 1

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJB008 Page Number : A2 of A3
Report Issued Date : Apr. 08, 2015
Report Version : Rev. 01

Report No.: FC530506


C Test Report No.: FC530506

## Mode 3

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJB008 Page Number : A3 of A3
Report Issued Date : Apr. 08, 2015
Report Version : Rev. 01