# Appendix A. Setup Photographs

#### <Conducted Emission>

#### Mode 1



Mode 5



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : A1 of A4
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01

Report No. : FC511301-30



## <Conducted Emission for Spot Check>

#### Mode 1



Mode 2




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : A2 of A4
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01


### <Radiated Emission>

#### Mode 5

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : A3 of A4
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01

Report No. : FC511301-30




## <Radiated Emission for Spot Check>

#### Mode 1

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : A4 of A4
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01

Report No. : FC511301-30