

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001 Page Number : C1 of C2
Report Issued Date : Apr. 06, 2015
Report Version : Rev. 01

Report No.: FR511301C




Report No.: FR511301C


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001

Page Number : C2 of C2 Report Issued Date: Apr. 06, 2015 Report Version : Rev. 01