Appendix D. SAR Test Setup Photos

Without Holster

<Receiver 1>:






Report No. : FA611504-04

Right Cheek








Left Cheek

Left Tilted

<Receiver 2>:







Report No. : FA611504-04

Right Cheek







Left Cheek

Left Tilted

Issued Date: May 26, 2016

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

FCC ID : 2ACCJA019 Page D2 of D6 Form version. : 151208





Report No. : FA611504-04

Front, Test Separation 10 mm

Back, Test Separation 10 mm



Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

Issued Date: May 26, 2016 Form version. : 151208 FCC ID: 2ACCJA019 Page D3 of D6





Report No. : FA611504-04

Front, Test Separation 15 mm


Back, Test Separation 15 mm

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

Issued Date: May 26, 2016 Form version. : 151208 Page D4 of D6 FCC ID: 2ACCJA019

With Holster

<Receiver 1>:






Report No. : FA611504-04

Right Cheek

Left Cheek

<Receiver 2>:





Right Cheek

Left Cheek



Left Tilted

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

Issued Date: May 26, 2016 Page D5 of D6 Form version. : 151208 FCC ID: 2ACCJA019





Back, Test Separation 10 mm



Report No. : FA611504-04

Bottom Side, Test Separation 10 mm



Front, Test Separation 15 mm



Back, Test Separation 15 mm

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

Issued Date: May 26, 2016 Page D6 of D6 Form version. : 151208 FCC ID: 2ACCJA019