

## Appendix C. Setup Photographs

### <Conducted Emission>

#### Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019 Page Number : C1 of C2
Report Issued Date : May 26, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.1

Report No.: FR611504-04B


# <Radiated Emission>

#### Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA019 Page Number : C2 of C2
Report Issued Date : May 26, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0/4.2 Version 1.1

Report No.: FR611504-04B