Appendix A. Setup Photographs

<Conducted Emission>

Mode 3



Mode 6



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN008 Page Number : A1 of A3
Report Issued Date : Jul. 08, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.1

Report No.: FC652006


<Radiated Emission>

Mode 3

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN008 Page Number : A2 of A3
Report Issued Date : Jul. 08, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.1

Report No.: FC652006


C Test Report No. : FC652006

Mode 6

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN008 Page Number : A3 of A3
Report Issued Date : Jul. 08, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1