

Report No.: FR511301-30E

# **Appendix C. Setup Photographs**

## <Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : C1 of C3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01




## Report No.: FR511301-30E

#### <Radiated Emission>

Y Plane

LF



#### HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002 Page Number : C2 of C3
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01






Report No.: FR511301-30E


# <Radiated Emission for Spot Check>

**Z** Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN002

Page Number : C3 of C3 Report Issued Date: Mar. 07, 2016

Report Version : Rev. 01