


Appendix D. Test Setup Photos


Top Receiver Worked



Front View



Left Side View



Right Side View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : D1 of D2
Report Issued Date : Apr. 22, 2016

Report No.: HA611504


Report Version : Rev. 01




Bottom Receiver Worked



Front View



Left Side View



Right Side View

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJA015 Page Number : D2 of D2
Report Issued Date : Apr. 22, 2016
Report Version : Rev. 01

Report No.: HA611504