

Report No. :FR670507E

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC: 2ACCJB066 Page Number : D1 of D2
Report Issued Date : Aug. 16, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15EWLB4 Version 1.4




Report No.:FR670507E


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC: 2ACCJB066 Page Number : D2 of D2
Report Issued Date : Aug. 16, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 Version 1.4