
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 2




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB018 Page Number : A1 of A3
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No. : FC551802

<Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB018 Page Number : A2 of A3
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01

Report No. : FC551802


Report No. : FC551802

Mode 2

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB018 Page Number : A3 of A3
Report Issued Date : Jun. 19, 2015
Report Version : Rev. 01