
SAR Test Report No. :FA511301

Appendix D. SAR Test Setup Photos


Top Receiver Worked:






Right Cheek


Right Tilted





Left Cheek Left Tilted

Bottom Receiver Worked:





Report No.: FA511301

Right Cheek




Right Tilted



Left Cheek **Left Tilted**

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958 Issued Date: Apr. 10, 2015 FCC ID: 2ACCJN001 Form version. : 141020 Page D2 of D4






Front, Test Separation 1 cm




Report No. : FA511301

Back, Test Separation 1 cm



Left Side, Test Separation 1 cm



Right Side, Test Separation 1 cm




Top Side, Test Separation 1 cm




Bottom Side, Test Separation 1 cm

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

Issued Date: Apr. 10, 2015 Form version. : 141020 FCC ID: 2ACCJN001 Page D3 of D4






Back, Test Separation 0 cm



Bottom Side, Test Separation 0 cm



Back with headset 1, Test Separation 1 cm



Back with headset 2, Test Separation 1 cm

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

Issued Date: Apr. 10, 2015 Form version. : 141020 FCC ID: 2ACCJN001 Page D4 of D4