

5F, C building, No. 232, Liang Jing Road ZhangJiang High-Tech Park, Pudong Area Shanghai, P.R. China. 201203 TEL: +86(0)21 61460666

TEL: +86(0)21 61460666 FAX: +86(0)21 61460602

Declaration of changes from Initial GFlip2 AT&T (40440) to Variant GFlip2 CC (4044L)

General: 4044L is a variant product of 4044O:

SOFTWARE MODIFICATIONS:

Protocol Stack changes: No

MMS/STK/USAT/USIM changes: NO

DM/SUPL/VT/FUMO/SWP/HCI: Remove DM & OMA FOTA

Other changes detail: Remove WiFi feature and Tethering/ several applications

• HARDWARE MODIFICATIONS:

Baseband changes: NO

> Band changes: NO

| product | GSM | UMTS | LTE |
|---------|-------------------|-------------|-------------|
| 40440 | 850/900/1800/1900 | FDD II/IV/V | B2/4/5/7/12 |
| 4044L | 850/900/1800/1900 | FDD II/IV/V | B2/4/5/7/12 |

Antenna changes: NOPCB Layout changes: NO

Main components changes:

| | Base Band | Transceiver | ASM | Power Amplifier | Tx SAW Filter | Rx SAW Filter(SAW Duplexer) |
|----------|-----------|-------------|-----|-----------------|---------------|-----------------------------|
| GSM 850 | NO | NO | NO | NO | N/A | NO |
| GSM 900 | NO | NO | NO | NO | N/A | NO |
| GSM 1800 | NO | NO | NO | NO | N/A | NO |
| GSM 1900 | NO | NO | NO | NO | N/A | NO |

| | Base Band | Transceiver | ASM | Power Amplifier | Tx SAW Filter | Rx SAW Filter(SAW Duplexer) |
|-------------|-----------|-------------|-----|-----------------|---------------|-----------------------------|
| UMTS FDD II | NO | NO | NO | NO | NA | NO |
| UMTS FDD IV | NO | NO | NO | NO | N/A | NO |
| UMTS FDD V | NO | NO | NO | NO | N/A | NO |

| | Base Band | Transceiver | ASM | Power Amplifier | Tx SAW Filter | Rx SAW Filter(SAW Duplexer) |
|---------|-----------|-------------|-----|-----------------|---------------|-----------------------------|
| LTE B2 | NO | NO | NO | No | N/A | NO |
| LTE B4 | NO | NO | NO | NO | N/A | NO |
| LTE B5 | NO | NO | NO | NO | N/A | NO |
| LTE B12 | NO | NO | NO | NO | N/A | NO |
| LTE B17 | NO | NO | NO | NO | N/A | NO |

| | Antanna | AP | MODEM | Transceiver | Balun | Band pass filter | diplexer |
|-----------|---------|----|-------|-------------|-------|------------------|----------|
| Bluetooth | NO | NO | NO | NO | N/A | NO | NO |
| wifi | NO | NO | NO | NO | N/A | NO | NO |

Bluetooth changes: NO

WiFi changes: NO

> FM changes: NO

Other components changes: NO TP/LCD/ Camera changes: NO

Other changes detailed:

4044O 2G GPRS/EGPRS Class is 10; 4044L 2G GPRS/EGPRS Class is 12

4044O doesn't support DC-HSDPA(Rel8); 4044L supports DC-HSDPA(Rel8), category is 24.

The charger is different.

• MECHANICAL MODIFICATIONS:

Use new metal front/back cover or keypad: NO

Mechanical shell changes: NO

Whole size of EUT: NO

Distance of Ear reference point to bottom of handset: NO Other trinkets to change the surface of handset: NO

> Other changes detailed: NO

APPROVED BY:

Project Manager: Liu Xudong Signature: Date: 2016/7/19