

Report No.:FR670507D

## Appendix D. Setup Photographs

# <Conducted Emission>

#### Mode 1



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC: 2ACCJB066 Page Number : D1 of D2
Report Issued Date : Aug. 16, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL Version 1.4




### Report No.:FR670507D


### <Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC: 2ACCJB066 Page Number : D2 of D2
Report Issued Date : Aug. 16, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL Version 1.4