

Report No.: FR612205D

Appendix C. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB052

Page Number : C1 of C2 Report Issued Date: Feb. 29, 2016 Report Version : Rev. 01


Report Template No.: BU5-FR15EWL Version 1.2

Report No. : FR612205D

<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB052 Page Number : C2 of C2
Report Issued Date : Feb. 29, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL Version 1.2