


est Report No. : FA552902


Appendix D. SAR Test Setup Photos





Right Cheek


Right Tilted





Left Cheek

Left Tilted







Bottom Face, Test Separation 1.0 cm

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

FCC ID: 2ACCJN004

Page D1 of D3

Issued Date : Jul. 31, 2015

Form version. : 150415




Report No.: FA552902

Edge1, Test Separation 0 cm

Edge1, Test Separation 0.9 cm




Edge2, Test Separation 0 cm



Edge2, Test Separation 0.1 cm



Edge3, Test Separation 0 cm



Edge4, Test Separation 0 cm

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958


FCC ID: 2ACCJN004


Page D2 of D3

Issued Date : Jul. 31, 2015

Form version.

: 150415






Bottom Face with Headset 2, Test Separation 0 cm



Bottom Face with Headset 2, Test Separation 1.0 cm



Bottom Face with Headset 1, Test Separation 1.0 cm

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

FCC ID: 2ACCJN004

Page D3 of D3

Issued Date : Jul. 31, 2015

Form version. : 150415