Appendix A. Setup Photographs

<Conducted Emission>

Mode 7



Mode 5



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001 Page Number : A1 of A3
Report Issued Date : Apr. 06, 2015
Report Version : Rev. 01

Report No. : FC511301


<Radiated Emission>

Mode 6

LF



HF




SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001 Page Number : A2 of A3
Report Issued Date : Apr. 06, 2015
Report Version : Rev. 01


Report No.: FC511301

Mode 5

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN001 Page Number : A3 of A3
Report Issued Date : Apr. 06, 2015
Report Version : Rev. 01

Report No. : FC511301