
Appendix D. SAR Test Setup Photos

Top Receiver Worked:







Report No. : FA511301-30

Right Cheek


Right Tilted





Left Cheek Left Tilted

Bottom Receiver Worked:







Report No. : FA511301-30

Right Cheek







Issued Date: Mar. 07, 2016

Left Cheek Left Tilted

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

FCC ID: 2ACCJN002 Page D2 of D4 Form version.: 151208





Front, Test Separation 1 cm



Report No. : FA511301-30

Back, Test Separation 1 cm



Left Side, Test Separation 1 cm



Right Side, Test Separation 1 cm



Top Side, Test Separation 1 cm




Bottom Side, Test Separation 1 cm

TEL: 86-0512-5790-0158 / FAX: 86-0512-5790-0958

Issued Date: Mar. 07, 2016 Form version. : 151208 FCC ID: 2ACCJN002 Page D3 of D4





Back, Test Separation 0 cm



Bottom Side, Test Separation 0 cm



Back with headset, Test Separation 1 cm