
3. Internal Photograph of EUT

Model Name: 7053E

Report No.: EP591604




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 12 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591604



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 13 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01


Report No.: EP591604



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 14 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01




Report No.: EP591604




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 15 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591604




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 16 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591604




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 17 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591604




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 18 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591604




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 19 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591604



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 20 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01


Report No.: EP591604



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034


: 21 of 40 Page Number Report Issued Date : Oct. 30, 2015 : Rev. 01 Report Version

Report No.: EP591604




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 22 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591604




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 23 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591604



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 24 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01

Report No.: EP591604



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB034 Page Number : 25 of 40
Report Issued Date : Oct. 30, 2015
Report Version : Rev. 01