

Report No.: FR592401-01C

Appendix C. Setup Photographs

<Conducted Emission>




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB031 Page Number : C1 of C2
Report Issued Date : Nov. 10, 2015
Report Version : Rev. 01




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB031 Page Number : C2 of C2
Report Issued Date : Nov. 10, 2015
Report Version : Rev. 01

Report No.: FR592401-01C