

Report No.: FR511301-29F

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005

Page Number : C1 of C2 Report Issued Date: Mar. 07, 2016 Report Version : Rev. 01




Report No. : FR511301-29F


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN005 Page Number : C2 of C2
Report Issued Date : Mar. 07, 2016
Report Version : Rev. 01