
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 3



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB030 Page Number : A1 of A3
Report Issued Date : Sep. 28, 2015
Report Version : Rev. 01


Report No. : FC582702

<Radiated Emission>

Mode 2

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB030 Page Number : A2 of A3
Report Issued Date : Sep. 28, 2015
Report Version : Rev. 01


Report No. : FC582702

C Test Report No. : FC582702


Mode 3

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB030 Page Number : A3 of A3
Report Issued Date : Sep. 28, 2015
Report Version : Rev. 01