

## Appendix B. Setup Photographs

## <Conducted Emission>

## Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN008 Page Number : B1 of B2
Report Issued Date : Jul. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR652006A







## <Radiated Emission>

**Z** Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2ACCJN008 Page Number : B2 of B2
Report Issued Date : Jul. 08, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR652006A