
Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB056

Page Number Report Issued Date: May 17, 2016 Report Version : Rev. 01 Report Template No.: BU5-FR15CBT4.0 Version 1.3

: B1 of B3

Report No.: FR631706B


<Radiated Emission>

Laptop Plane

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB056 Page Number : B2 of B3
Report Issued Date : May 17, 2016
Report Version : Rev. 01

Report No.: FR631706B


Report Template No.: BU5-FR15CBT4.0 Version 1.3

Z Plane

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACCJB056 Page Number : B3 of B3
Report Issued Date : May 17, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 1.3

Report No.: FR631706B