

Inside view of EUT



Report no. ETLE140402.0468, Page D1 of D21




Inside view of EUT



Report no. ETLE140402.0468, Page D2 of D21




Top side view of main board



Report no. ETLE140402.0468, Page D3 of D21




Top side view of main board (case open)



Report no. ETLE140402.0468, Page D4 of D21




Top side view of main board (without camera lens)



Report no. ETLE140402.0468, Page D5 of D21



Bottom side view of main board



Report no. ETLE140402.0468, Page D6 of D21




Bottom side view of main board (case open)



Report no. ETLE140402.0468, Page D7 of D21




Top side view of power board



Report no. ETLE140402.0468, Page D8 of D21




Top side view of power board (case open)



Report no. ETLE140402.0468, Page D9 of D21



Bottom side view of power board



Report no. ETLE140402.0468, Page D10 of D21




Top side view of RF Module



Report no. ETLE140402.0468, Page D11 of D21



Top side view of RF Module (case open)



Report no. ETLE140402.0468, Page D12 of D21




Bottom side view of RF Module



Report no. ETLE140402.0468, Page D13 of D21



Bottom side view of RF Module (case open)



Report no. ETLE140402.0468, Page D14 of D21




Top side view of RF Module and Antenna



Report no. ETLE140402.0468, Page D15 of D21



Top side view of GPS Module



Report no. ETLE140402.0468, Page D16 of D21



Bottom side view of GPS Module



Report no. ETLE140402.0468, Page D17 of D21



Bottom side view of GPS Module (case open)




Report no. ETLE140402.0468, Page D18 of D21



View of camera lens






Report no. ETLE140402.0468, Page D19 of D21




Top side view of image sensor board



Report no. ETLE140402.0468, Page D20 of D21



Bottom side view of image sensor board



Report no. ETLE140402.0468, Page D21 of D21