

Appendix A. Test Photos

Report No.: FR581324AN

SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





Report No. : FR581324AN

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A7

Report Version : Rev. 01





Report No.: FR581324AN

SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






Report No.: FR581324AN

2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A4 of A7

Report Version


: Rev. 01




FCC Test Report

Report No.: FR581324AN

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A7

Report Version


: Rev. 01



FCC Test Report

Report No.: FR581324AN

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A7

Report Version

: Rev. 01







Report No.: FR581324AN

EUT take a close-up

SPORTON INTERNATIONAL INC. Page No. : A7 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973