

Report No. : FR462628AC

Appendix A. Test Photos

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR462628AC

1 Photographs of Conducted Emissions Test Configuration

Mode 1



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A6

Report Version

: Rev. 01






SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01




For radiated emissions 30MHz~1GHz

Mode 1



FRONT VIEW



: A5 of A6

: Rev. 01


REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version




For radiated emissions above 1GHz

Mode 1



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01