



Appendix A. Test Photos1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A6

Report Version


: Rev. 01

Report No. : FR650618





Report No.: FR650618



Side view

SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





2. hotographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A3 of A6 Report Version : Rev. 01

Report No. : FR650618




FCC Test Report


Report No. : FR650618

For radiated emissions 30MHz~1GHz

Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A6

Report Version

: Rev. 01



FCC Test Report

Report No.: FR650618

For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6

Report Version

: Rev. 01



FCC Test Report No.: FR650618



EUT take a close-up

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973