


Test Photos Appendix H

1. Photographs of Conducted Emissions Test Configuration



Front View




Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973



Test Photos Appendix H



Under Table View

SPORTON INTERNATIONAL INC. Page No.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 950915

: H2 of H4




Appendix H **Test Photos**

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 30MHz~1GHz



Front View



Rear View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973




Test Photos Appendix H

For radiated emissions above 1GHz



Front View



Rear View

—THE END——

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973