



Test data continued from report number: 103224477MPK-002A


Plot 4.25
Ant 0, Tx @ 2412MHz 802.11n 20MHz




Plot 4.26
Ant 0, Tx @ 2437MHz 802.11n 20MHz




Plot 4.27
Ant 0, Tx @ 2462MHz 802.11n 20MHz




Plot 4.28
Ant 1, Tx @ 2412MHz 802.11n 20MHz





Plot 4.29
Ant 1, Tx @ 2437MHz 802.11n 20MHz




Plot 4.30
Ant 1, Tx @ 2462MHz 802.11n 20MHz






Plot 4.31
Ant 2, Tx @ 2412MHz 802.11n 20MHzPlot 4.32
Ant 2, Tx @ 2437MHz 802.11n 20MHz

Plot 4.33
Ant 2, Tx @ 2462MHz 802.11n 20MHz




Plot 4.34
Ant 3, Tx @ 2412MHz 802.11n 20MHz






Plot 4.35
Ant 3, Tx @ 2437MHz 802.11n 20MHzPlot 4.36
Ant 3, Tx @ 2462MHz 802.11n 20MHz

Plot 4.37
Ant 0, Tx @ 2412MHz 802.11n 40MHz




Plot 4.38
Ant 0, Tx @ 2437MHz 802.11n 40MHz



Plot 4.39
Ant 0, Tx @ 2462MHz 802.11n 40MHzPlot 4.40
Ant 1, Tx @ 2412MHz 802.11n 40MHz

Plot 4.41
Ant 1, Tx @ 2437MHz 802.11n 40MHz



Plot 4.42
Ant 1, Tx @ 2462MHz 802.11n 40MHz

