




Plot 4.9  
**Ant 2, Tx @ 2462MHz 802.11b**




Plot 4.10  
**Ant 3, Tx @ 2412MHz 802.11b**





Plot 4.11  
**Ant 3, Tx @ 2437MHz 802.11b**




Plot 4.12  
**Ant 3, Tx @ 2462MHz 802.11b**




Plot 4.13  
**Ant 0, Tx @ 2412MHz 802.11g**Plot 4.14  
**Ant 0, Tx @ 2437MHz 802.11g**


Plot 4.15  
Ant 0, Tx @ 2462MHz 802.11g




Plot 4.16  
Ant 1, Tx @ 2412MHz 802.11g







Plot 4.17  
Ant 1, Tx @ 2437MHz 802.11g




Plot 4.18  
Ant 1, Tx @ 2462MHz 802.11g




Plot 4.19  
**Ant 2, Tx @ 2412MHz 802.11g**Plot 4.20  
**Ant 2, Tx @ 2437MHz 802.11g**

Plot 4.21  
**Ant 2, Tx @ 2462MHz 802.11g**Plot 4.22  
**Ant 3, Tx @ 2412MHz 802.11g**

Plot 4.23  
Ant 3, Tx @ 2437MHz 802.11g



Plot 4.24  
Ant 3, Tx @ 2462MHz 802.11g



Test data continued in report number: 103224477MPK-002B (Pages: 127 to 194)