



# 1 Photographs of Conducted Emissions Test Configuration



Report No.: FR452748


FRONT VIEW



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01






**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01




## 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 




**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A3 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01



For radiated emissions 30MHz~1GHz



**FRONT VIEW** 




**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A4 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01



### For radiated emissions above 1GHz



### **FRONT VIEW**



#### **REAR VIEW**

SPORTON INTERNATIONAL INC. Page No. : A5 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01