

Toronto July 15, 2014

To Whom It May Concern

Re: Tuning Procedure for the DRU-200 (FCC ID: 2ACLT-DRU200)

This is to affirm that a tuning procedure for the DRU-200 is not required as the signal outputs are at a fixed frequency and bandwidth. As such, no tuning procedure has been submitted as part of the FCC application.

Regards,

Ána Maria De Valencia

Senior Manager, Government Relations

UBS Ltd.

400 Spinnaker Way

Vaughan, ON

CANADA L4K 5Y9 905 669 8533 x 141

905 669 8516 fax

416 271 7012 cell

www.uniquesys.com