Appendix A. Test Photos

Report No.: FR461355


SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01



1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01





SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A3 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01




2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW




REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A4 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01



For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456


FAX: 886-3-327-0973

Page No. : A5 of A7


Report Version : Rev. 01



For radiated emissions above 1GHz



FRONT VIEW



Page No.

Report Version


: A6 of A7

: Rev. 01


REAR VIEW

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456





EUT take a close-up



EUT take a close-up

SPORTON INTERNATIONAL INC. Page No. : A7 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01