
1. External Photograph of EUT

Brand Name: Tramigo; Model Name: T23 Fleet


Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 1 of 28
Report Issued Date : Jul. 30, 2014



Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304

Page Number : 2 of 28 Report Issued Date: Jul. 30, 2014

: Rev. 01 Report Version

Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 3 of 28
Report Issued Date : Jul. 30, 2014

: Rev. 01

Report Version

Report No.: EP470201


Brand Name: Tramigo; Model Name: T23 Fleet



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 4 of 28
Report Issued Date : Jul. 30, 2014



Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304

Page Number : 5 of 28 Report Issued Date: Jul. 30, 2014

Report No.: EP470201

Brand Name: Tramigo; Model Name: T23 Fleet



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 6 of 28
Report Issued Date : Jul. 30, 2014

Photograph of Accessory 2.

Brand Name: Tramigo; Model Name: T23 Fleet

Report No.: EP470201

List of Accessory:


Specification of Accessory		
Battery	Brand Name	Tramigo
	Model Name	T22-BAT(B6)
USB Cable	Brand Name	Tramigo
	Model Name	T23-USB
	Signal Line Type	0.4m, shielded cable, without core
Power cable	Brand Name	Tramigo
	Model Name	T23-IO
	Signal Line Type	2m, non-shielded cable, without core
Optional Microphone	Brand Name	Tramigo
	Model Name	T23-AMIC
	Signal Line Type	3m, non-shielded cable, without core
External GPS Antenna	Brand Name	Tramigo
	Model Name	T23-GPS
	Signal Line Type	2m, non-shielded cable, without core

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (SHENZHEN) INC. Page Number : 7 of 28 TEL: 86-755-3320-2398 Report Issued Date: Jul. 30, 2014 Report Version : Rev. 01

FCC ID: 2ACP3-T-1304


Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304 Page Number : 8 of 28
Report Issued Date : Jul. 30, 2014



Report No.: EP470201



TEL: 86-755-3320-2398 FCC ID: 2ACP3-T-1304

Page Number : 9 of 28 Report Issued Date: Jul. 30, 2014