


Version.1.3 Page 61 of 78








Version.1.3 Page 62 of 78








Version.1.3 Page 63 of 78








Version.1.3 Page 64 of 78








Version.1.3 Page 65 of 78








Version.1.3 Page 66 of 78








Version.1.3 Page 67 of 78








Version.1.3 Page 68 of 78






Report No.: S19061201012001

Condition	Mode	Frequency (MHz)	Antenna	Max Value (dBc)	Limit	Verdict
					(dBc)	
NVNT	1-DH5	2402	Ant 1	-54.89736519814	-20	Pass
NVNT	1-DH5	2441	Ant 1	-51.77939942598	-20	Pass
NVNT	1-DH5	2480	Ant 1	-51.96831144333	-20	Pass
NVNT	2-DH5	2402	Ant 1	-54.71914167404	-20	Pass
NVNT	2-DH5	2441	Ant 1	-54.86426270008	-20	Pass
NVNT	2-DH5	2480	Ant 1	-49.59238337517	-20	Pass
NVNT	3-DH5	2402	Ant 1	-50.18990120888	-20	Pass
NVNT	3-DH5	2441	Ant 1	-50.13043650627	-20	Pass
NVNT	3-DH5	2480	Ant 1	-48.72366019249	-20	Pass






Version.1.3 Page 69 of 78








Version.1.3 Page 70 of 78








Version.1.3 Page 71 of 78








Version.1.3 Page 72 of 78








Version.1.3 Page 73 of 78








Version.1.3 Page 74 of 78








Version.1.3 Page 75 of 78








Version.1.3 Page 76 of 78








Version.1.3 Page 77 of 78







**END OF REPORT** 

Version.1.3 Page 78 of 78