# Appendix E. Setup Photographs

### <Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID: 2ACQO-LBVI0000001

Page Number : E1 of E3
Report Issued Date : Mar. 03, 2017
Report Version : Rev. 01

Report No. : FR710415A

Report Template No.: BU5-FR15CBT Version 2.0





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID: 2ACQO-LBVI0000001

Page Number : E2 of E3
Report Issued Date : Mar. 03, 2017
Report Version : Rev. 01


Report No. : FR710415A

Report Template No.: BU5-FR15CBT Version 2.0


# <Radiated Emission>

# X Plane

LF



HF



### SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID: 2ACQO-LBVI0000001

Page Number : E3 of E3
Report Issued Date : Mar. 03, 2017
Report Version : Rev. 01

Report No. : FR710415A

Report Template No.: BU5-FR15CBT Version 2.0