## Appendix F. Setup Photographs

## <Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID: 2ACQO-LBVI0000001

Page Number : F1 of F3
Report Issued Date : Mar. 03, 2017
Report Version : Rev. 01

Report No. : FR710415B

Report Template No.: BU5-FR15CBT4.0 Version 2.0





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID: 2ACQO-LBVI0000001

Page Number : F2 of F3 Report Issued Date: Mar. 03, 2017

Report Version

: Rev. 01


Report No. : FR710415B

Report Template No.: BU5-FR15CBT4.0 Version 2.0


## <Radiated Emission>

## X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

FCC ID: 2ACQO-LBVI0000001

Page Number : F3 of F3
Report Issued Date : Mar. 03, 2017
Report Version : Rev. 01

Report No. : FR710415B

Report Template No.: BU5-FR15CBT4.0 Version 2.0