


FCC Test Report

APPENDIX B. Photographs of EUT




Report No. : EP462324-01




TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B1 OF B8
ISSUED DATE : Sep. 29, 2014







Report No. : EP462324-01



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : B2 OF B8
ISSUED DATE : Sep. 29, 2014