

## **Appendix A. Test Photos**

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





## 1 Photographs of Conducted Emissions Test Configuration

Mode 2



## **FRONT VIEW**



**REAR VIEW** 

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A2 of A6 Report Version : Rev. 01







**SIDE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






## 2 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A6

Report Version

: Rev. 01




FCC Test Report


Report No. : FR462324-02AN

For radiated emissions 30MHz~1GHz

Mode 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6
Report Version : Rev. 01




FCC Test Report


Report No. : FR462324-02AN

For radiated emissions above 1GHz

Mode 1



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973