
## 3. Internal Photograph of EUT

Brand Name: Hi-P; Model Name: H450R


Report No.: EP551401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R Page Number : 12 of 29
Report Issued Date : Jul. 21, 2015
Report Version : Rev. 01



Report No.: EP551401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R

Page Number : 13 of 29 Report Issued Date : Jul. 21, 2015 Report Version : Rev. 01



Report No.: EP551401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R

: 14 of 29 Page Number Report Issued Date : Jul. 21, 2015 Report Version : Rev. 01



Report No.: EP551401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R

: 15 of 29 Page Number Report Issued Date : Jul. 21, 2015 Report Version : Rev. 01



Report No.: EP551401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R

Page Number : 16 of 29 Report Issued Date : Jul. 21, 2015 Report Version : Rev. 01



Report No.: EP551401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R

Page Number : 17 of 29 Report Issued Date : Jul. 21, 2015 Report Version : Rev. 01



Report No.: EP551401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R

: 18 of 29 Page Number Report Issued Date : Jul. 21, 2015 Report Version : Rev. 01



Report No.: EP551401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R

Page Number : 19 of 29 Report Issued Date : Jul. 21, 2015 Report Version : Rev. 01



Report No.: EP551401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R


Page Number : 20 of 29 Report Issued Date : Jul. 21, 2015 Report Version : Rev. 01

Report No.: EP551401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R Page Number : 21 of 29
Report Issued Date : Jul. 21, 2015
Report Version : Rev. 01


Report No.: EP551401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R

Page Number : 22 of 29 Report Issued Date : Jul. 21, 2015 Report Version : Rev. 01


Report No.: EP551401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R Page Number : 23 of 29
Report Issued Date : Jul. 21, 2015
Report Version : Rev. 01




Report No.: EP551401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R


Page Number : 24 of 29 Report Issued Date : Jul. 21, 2015 Report Version : Rev. 01

Report No.: EP551401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R Page Number : 25 of 29
Report Issued Date : Jul. 21, 2015
Report Version : Rev. 01

Report No.: EP551401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R Page Number : 26 of 29
Report Issued Date : Jul. 21, 2015
Report Version : Rev. 01

Report No.: EP551401




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R Page Number : 27 of 29
Report Issued Date : Jul. 21, 2015
Report Version : Rev. 01

Report No.: EP551401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R Page Number : 28 of 29
Report Issued Date : Jul. 21, 2015
Report Version : Rev. 01

Report No.: EP551401



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2ACUZH450R Page Number : 29 of 29
Report Issued Date : Jul. 21, 2015
Report Version : Rev. 01