1. External Photograph of EUT

Brand Name: rooti / Model Name: CliMate / Marketing Name: CliMate

Report No.: EP471708



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACVP-E1-2014 Page Number : 1 of 15
Report Issued Date : Aug. 15, 2014
Report Version : Rev. 01



Brand Name: rooti / Model Name: CliMate / Marketing Name: CliMate

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACVP-E1-2014 Page Number : 2 of 15
Report Issued Date : Aug. 15, 2014
Report Version : Rev. 01

Report No.: EP471708

2. Photograph of Accessory

Brand Name: rooti / Model Name: CliMate / Marketing Name: CliMate

Report No.: EP471708

Specification of Accessory		
IBattery	Brand Name	SONY
	Model Name	CR2032
lCradle	Brand Name	N/A
	Model Name	N/A

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACVP-E1-2014 Page Number : 3 of 15 Report Issued Date : Aug. 15, 2014

Report Version : Rev. 01



Brand Name: rooti / Model Name: CliMate / Marketing Name: CliMate

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACVP-E1-2014 Page Number : 4 of 15 Report Issued Date : Aug. 15, 2014

Report No.: EP471708

Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACVP-E1-2014 Page Number : 5 of 15 Report Issued Date : Aug. 15, 2014

Report No.: EP471708

Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACVP-E1-2014 Page Number : 6 of 15 Report Issued Date : Aug. 15, 2014

Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2ACVP-E1-2014 Page Number : 7 of 15

Report Issued Date : Aug. 15, 2014

Report No.: EP471708

Report Version : Rev. 01