Report No.: 14121030HKG-001

#### **Equipment Photographs**

Model: TM-MC3888U

(Internal)






Report No.: 14121030HKG-001

## **Equipment Photographs**

Model: TM-MC3888U

(Internal)





Report No.: 14121030HKG-001

## **Equipment Photographs**

Model: TM-MC3888U

(Internal)







Report No.: 14121030HKG-001

## **Equipment Photographs**

Model: TM-MC3888U

(Internal)







Report No.: 14121030HKG-001

#### **Equipment Photographs**

Model: TM-MC3888U

(Internal)







Report No.: 14121030HKG-001

## **Equipment Photographs**

Model: TM-MC3888U

(Internal)







Report No.: 14121030HKG-001

## **Equipment Photographs**

Model: TM-MC3888U

(Internal)





Report No.: 14121030HKG-001

#### **Equipment Photographs**

Model: TM-MC3888U

(Internal)







Report No.: 14121030HKG-001

## **Equipment Photographs**

Model: TM-MC3888U

(Internal)





Report No.: 14121030HKG-001

#### **Equipment Photographs**

Model: TM-MC3888U

(Internal)







Report No.: 14121030HKG-001

## **Equipment Photographs**

Model: TM-MC3888U

(Internal)







Report No.: 14121030HKG-001

## **Equipment Photographs**

Model: TM-MC3888U

(Internal)





Report No.: 14121030HKG-001

## **Equipment Photographs**

Model: TM-MC3888U

(Internal)







Report No.: 14121030HKG-001

# **Equipment Photographs**

Model: TM-MC3888U

(Internal)





Report No.: 14121030HKG-001

# **Equipment Photographs**

Model: TM-MC3888U

(Internal)

