

ANNEX B TEST SETUP PHOTOS

B.1 Radiated Field Strength Measurement

Below 1 GHz



30 MHz-1 GHz (USB test mode)


Above 1 GHz



USB test mode



B.2 Conducted Emission



USB Test Mode