

Test report No. : 10987173H-A Page : 63 of 68

FCC ID : 2ACZS-WG30W01 Issue date : December 14, 2015

# **APPENDIX 4: Photographs of test setup**

# 1. Photographs of EUT





4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10987173H-A Page : 64 of 68

FCC ID : 2ACZS-WG30W01 Issue date : December 14, 2015

# 2. Photographs of host device













UL Japan, Inc. Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10987173H-A Page : 65 of 68

FCC ID : 2ACZS-WG30W01 Issue date : December 14, 2015





# Another lens of an accessory






Test report No. : 10987173H-A Page : 66 of 68

FCC ID : 2ACZS-WG30W01 Issue date : December 14, 2015

# 3. Antenna position



Test report No. : 10987173H-A Page : 67 of 68

FCC ID : 2ACZS-WG30W01 Issue date : December 14, 2015


# 4. Photographs of setup



4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Test report No. : 10987173H-A Page : 68 of 68

FCC ID : 2ACZS-WG30W01 Issue date : December 14, 2015



**End of Report** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN