



Report No. : EP5N1918

APPENDIX B. Photographs of EUT





TEL: 886-3-327-3456 FAX: 886-3-327-0973




Report No. : EP5N1918







TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B2 of B14
Report Version : Rev. 01












Report No.: EP5N1918






TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B9 of B14
Report Version : Rev. 01




Report No. : EP5N1918






SPORTON International Inc.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page Number : B10 of B14
Report Version : Rev. 01






















Page Number : B12 of B14

Report Version : Rev. 01










Page Number : B13 of B14

Report Version : Rev. 01





Page Number : B14 of B14
Report Version : Rev. 01