

Appendix C. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AD3D-SB Page Number : C1 of C2
Report Issued Date : Oct. 28, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.0

Report No.: FR592202




Report No.: FR592202

<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AD3D-SB Page Number : C2 of C2
Report Issued Date : Oct. 28, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.0