


Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



Remote View



Rear View

Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AD9M-003A Page Number : D1 of D2
Report Issued Date : Jul. 04, 2019
Report Version : Rev. 01

Report No.: FR942441D


Report Template No.: BU5-FR15CNFC Version 2.0




Report No.: FR942441D

<Radiated Emission>

From 9kHz to 30MHz



From 30MHz to 1000 MHz



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AD9M-003A Page Number : D2 of D2
Report Issued Date : Jul. 04, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0