
Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for Band 2, 5, 7, 12

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID:2AD9M-003A Page Number : C1 of C2
Report Issued Date : Jul. 04, 2019
Report Version : Rev. 01


Report Template No.: BU5-FGLTE Version 2.0

Report No.: FG942441B


<Radiated Emission>

Z Plane for Band 4, 41

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID:2AD9M-003A Page Number : C2 of C2
Report Issued Date : Jul. 04, 2019
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0

Report No.: FG942441B