US Tech Test Report: FCC ID: Test Report Number: Issue Date: Customer: Model:

FCC Part 15 Certification 2AD9R-CO1501 15-0029 February 13, 2015 Controlant EHF CO 15.01

INTERNAL PHOTOGRAPHS




Figure 1. EUT with Case Removed

US Tech Test Report: FCC ID: Test Report Number: Issue Date: Customer: Model:

FCC Part 15 Certification 2AD9R-CO1501 15-0029 February 13, 2015 Controlant EHF CO 15.01




Figure 2. Back of EUT (antenna soldered to PCB)

US Tech Test Report: FCC ID: Test Report Number: Issue Date: Customer: Model: FCC Part 15 Certification 2AD9R-CO1501 15-0029 February 13, 2015 Controlant EHF CO 15.01




Figure 3. Front of EUT with Radio