May 6, 2019

Timco Engineering, Inc. 849 NW State Road 45 P.O. Box 370 Newberry, Florida 32669

Re: Justification for Label Location

FCC: 2AD9X-KFG

IC: 12637A-KFG

To Whom It May Concern:

Per our label location exhibit, we will place our label on the inside of the housing Lid. The outside of the small sensor housing would degrade the appearance of the sensor. The inside of the Lid is easily accessible and visible when accessing the battery.

Sincerely,

P. J. L. L. Justin Carlson

General Manager

Versa Wireless Inc.

103 - 19292 60th Avenue

Surrey, BC V3S 3M2

Canada